

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
(A4) Jetta, Jetta Wagon	2004 - 2005	1.9L (BEW)	All	All	All
Golf	2004 - 2005	1.9L (BEW)	AII	All	AII
New Beetle	2004 - 2005	1.9L (BEW)	AII	All	AII
(B5) Passat, Passat Wagon	2004 - 2005	2.0L (BHW)	AII	All	All
Touareg	2004	5.0L (BKW)	AII	All	All

Condition

01 08 33 Nov. 25, 2008 **2017520** Supersedes T. B. Group 01 Number 08-28 dated Oct. 22, 2008 to provide GFF allowance and change Touareg labor operation number in warranty table.

MIL ON, Glow Plug Faults Stored in ECM, Bosch Glow Plug System Only

MIL ON with glow plug faults present in ECM.

Technical Background

Conversion to a re-designed glow plug is necessary due to a change in supplier.

Production Solution

No production solution necessary, engine out of production.

Page 1 of 8 plus attachment



Service

One or more of the following fault codes may be stored in the ECM Fault Memory:

DTC	Description
P0671	Cylinder 1 Glow Plug Circuit
P0672	Cylinder 2 Glow Plug Circuit
P0673	Cylinder 3 Glow Plug Circuit
P0674	Cylinder 4 Glow Plug Circuit
P0675	Cylinder 5 Glow Plug Circuit
P0676	Cylinder 6 Glow Plug Circuit
P0677	Cylinder 7 Glow Plug Circuit
P0678	Cylinder 8 Glow Plug Circuit
P0679	Cylinder 9 Glow Plug Circuit
P0680	Cylinder 10 Glow Plug Circuit

- Diagnose cause of glow plug faults following normal diagnostic procedure
- Install replacement glow plugs Part No. N10591607 as a complete set.
- Update ECM software.

Note:

DO NOT install glow plugs Part No. N10591607 in an engine equipped with NGK glow plugs.

Failure to update ECM programming after installing new glow plugs will result in glow plug system failure.

Page 2 of 8 plus attachment

© 2008 Volkswagen Group of America, Inc.



PROCEDURE:

Engine Control Module Update - Programming (Flashing) using Software Version Management (SVM)

Note:

An Update Programming procedure (flash) may overwrite any "TUNED" ECM or TCM programming. A "TUNED" ECM or TCM is described as any ECM or TCM altered so as to perform outside the normal parameters and specifications approved by Volkswagen Group of America.

Current Tuned ECM or TCM requirements: If you encounter a vehicle with a "Tuned" ECM or TCM, your dealership must do the following before performing any procedure that updates ECM or TCM programming:

- Notify the owner that their ECM or TCM was found to have been tuned
- Notify the owner any damage caused by the tuning of the ECM or TCM (including any adverse emissions consequences) will not be covered by Volkswagen Group of America warranties.
- Obtain the owner's written consent (see attached Control Module Tuning form) for any requested repair under warranty or outside warranty that requires flashing, which will automatically overwrite the "Tuned" program.

If the vehicle has a tuned ECM or TCM, ensure the Control Module Tuning Form has been filled out.

Vehicle requirements

Battery MUST have minimum no-load charge of 12.5V (failure to maintain voltage during update process can lead to ECM failure) (use an Volkswagen approved Midtronics/InCharge 940 (INC-940) tester/charger to maintain battery voltage).

VAS 5051: connected to vehicle and to 110V AC Power supply at all times during procedure.

VAS 5052: connected to vehicle with battery voltage requirements met.

Any appliances with high electromagnetic radiation (i.e. mobile phones) switched OFF.

When performing the update programming procedure, ALL DTCs for all systems are erased.

DTCs linked to Guided Fault Finding function tests will be lost. Therefore, always address stored DTCs for Customer concerns unrelated to the update programming procedure first.

Note:

Non–observance of the following points may lead to ECM failure! VAS 5051 or VAS 5052 must always be connected to the approved power supply at the approved voltages. Under no circumstances should the power supply be interrupted or the diagnostic connector unplugged during the update programming procedure. Any appliances with high electromagnetic radiation (i.e. mobile phones) must be switched OFF.

Prior to launching VAS-PC application and starting control module update process, confirm tester screen saver and power settings in accordance with Special Tools and Equipment - Service Information Circular # VSE-08-18. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure.



i Tip:

To Update-Programming using SVM, review and follow instructions in Technical Bulletin Instance 2014603 "Software Version Management".

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.

Update the Engine Control Module using the SVM Unit code as listed in the table below: •

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
Jetta/Golf/	1.9L (BEW)	038 906 016H	6327	038 997 016L	1386	302D
Jetta Wagon			6210			
			5675			
			5375			
			5284			
			5263			
			5251			
			5167			
			4948			
			4782			
Jetta/Golf/	1.9L (BEW)	038 906 016Q	6110	038 997 016L	1386	302D
Jetta Wagon			5843			
Jetta/Golf/ Jetta Wagon	1.9L (BEW)	038 997 016H	8008	038 997 016L	1386	302D
New Beetle	1.9L (BEW)	038 906 016J	6328	038 997 016M	2878	302E
			6223			
			5443			
			5376			
			5285			
			5250			
			5168			
			4949			

Page 4 of 8 plus attachment

© 2008 Volkswagen Group of America, Inc.



New Beetle	1.9L (BEW)	038 906 016P	7000	038 997 016M	2878	302E
			6111			
			5859			
Passat	2.0L (BHW)	038 906 016L	6417	038 997 016N	1388	3047
			6036			
			5978			
			5656			
			5377			
Passat	2.0L (BHW)	038 906 016R	6416	038 997 016N	1388	3047
			6222			
Passat	2.0L (BHW)	038 906 016R	8900	038 997 016N	1388	3047
Touareg	5.0L (BKW)	070 906 016BG	<u>6366</u>	070 997 016R	2813	3046
	· · · /		5979			
			5676			

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.

The electric cooling fans may be activated during the ECM updating procedure.

i Tip:

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer (as required in SVM Technical Bulletin Instance 2014603).

Page 5 of 8 plus attachment



Warranty

To determine if the Procedures Manua		vered under Warra	anty, always refer	to the Warranty P	olicies and	
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To	
(A4) Jetta, Jetta Wagon	2004 - 2005	1.9L (BEW)	All	All	All	
Golf	2004 - 2005	1.9L (BEW)	All	All	All	
New Beetle	2004 - 2005	1.9L (BEW)	All	All	All	
(B5) Passat, Passat Wagon	2004 - 2005	2.0L (BHW)	All	All	All	
Touareg	2004	5.0L (BKW)	All	All	All	
Claim Type: Use applicable Claim Type ¹⁾						
		SAGA C	oding			
Service Number: Programming	Damage Code	Damage LocationParts Manufacturer(Depends on Service No.)(removed part)				
2360	0039	Use applicable when indicated in ElsaWeb (L/R)			_2)	
Service Number:	Damage	Damage Location		Parts Manufacturer		
Glow Plug	Code	(Depends on Service No.)		(removed part)		
2884	0012	Use applicable when indicated in ElsaWeb (L/R)			_2)	
Labor Operation ³⁾ : Programming, Jetta, Jetta Wagon		23382599 = 90 TL	J			
Labor Operation ³⁾ Replacement, Jett		28842000 = 70 TL	J			

Page 6 of 8 plus attachment

^{© 2008} Volkswagen Group of America, Inc.



Labor Operation ³⁾ : Programming, Golf	23382599 = 90 TU	
Labor Operation ³⁾ : Glow Plug Replacement, Golf	28842000 = 70 TU	
Labor Operation ³⁾ : Programming, New Beetle	23382599 = 90 TU	
Labor Operation ³⁾ : Glow Plug Replacement, New Beetle	28842000 = 70 TU	
Labor Operation ³⁾ : Programming, Passat, Passat Wagon	23602599 = 100 TU	
Labor Operation ³⁾ : Glow Plug Replacement, Passat, Passat Wagon	28842000 = 70 TU	
Labor Operation ³⁾ : Programming, Touareg	24702599 = 90 TU	
Labor Operation ³⁾ : Glow Plug Replacement (Touareg Only)	28842063 = 50 TU	
Labor Operation ³⁾ : Intake Manifold R&I (Touareg ONLY, predecessor to labor operation above)	23802013 = 250 TU	
	Diagnostic Time ⁴⁾	
GFF Time expenditure	01500000 = actual print time	YES
Road Test	01210002 & 01210004	NO
Technical Diagnosis	0132xxxx = XX TU max.	NO

Page 7 of 8 plus attachment

© 2008 Volkswagen Group of America, Inc.



¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only

²⁾ Code per warranty vendor code policy.

³⁾ Labor Time Units (TUs) are subject to change with Elsa updates.

⁴⁾ Documentation required per Warranty Policy & Procedures Manual.

Required Parts and Tools

Part Description	Part No:	Quantity
Glow Plug	N10591607	Engine Specific

Tool Description	Tool No:	Quantity
VAS Diagnostic Tool	VAS 5051 / 5052	1
(with Base CD V.14.00 and the Brand CD V.14.88.00 or higher)		

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

*) "TUNING" is described as the addition of or modification of any component which causes a Volkswagen vehicle to perform outside the normal parameters and specifications approved by Volkswagen Group of America, Inc..

Date:	
Dealer Number:	
Vehicle Identification Number:	
Repair Order Number:	
•	

Dealer stamp

, owner or driver of the above identified Volkswagen, confirm:

"Tuning" as described above (especially power increasing modifications) has NOT been performed on my vehicle.

"Tuning" as described above has been performed on my vehicle and the following components were modified or installed:

<u>TUNING was performed by (Please provide Company name and telephone number, if you wish us to contact them):</u>

I understand that if my Control Module is determined to have been tuned, any damage caused by the tuning of the Control Module (including adverse emissions consequences) will not be covered by Volkswagen Group of America, Inc. warranties.

I am permitting an authorized Volkswagen Dealer to reflash (update) my Control Module, and by doing so, I understand that this process will automatically overwrite (destroy) and permanently delete any tuning program that was previously installed on the Control Module of my Volkswagen vehicle.

By signing below, I fully acknowledge and understand that the tuning program will not be restored and Volkswagen Group of America, Inc., will not be liable in any way for the loss of tuning data.

Signature of Customer