

Subject: Runs Rough On Initial Start at Temperatures Below

-7°C (20°F)

Group: 23

Number: 05-02

Model(s): Golf, Jetta, Jetta Wagon, New Beetle with 1.9L 2V TDI PD (Eng. Code BEW)

2004, 2005

Date: Feb. 23, 2005

Supersedes T.B. Group 23 number 05-01 dated Feb. 3, 2005 due to Injector Labor Operation Update.

## **Condition**

Vehicle runs rough on initial start at cold temperatures (below -7°C (20°F).

### Service

- Workflow Overview for Service Procedures incorporated into this Technical Bulletin.
  - Verify that Work procedures in the following Technical bulletin (depending on model) have been performed:

### 2005 Models

If condition exists, install kit and Update ECM programming (flash) as follows.

### 2004 Models

Golf, Jetta, Jetta Wagon - Group 97 No: 04-05 (BG) (2004 only)

New Beetle - Group 97 No: 04-06 (BH) (2004 only).

If condition still exists, install Kit Part No: 038 198 073B\* and update ECM programming (flash) as follows:

Kit Part No: 038 198 073B* includes				
Part No:	Qty.	Description		
038 130 073 AG**	4	Fuel injectors		
N 105 916 04	4	Glow Plugs		
038 907 281C	1	Glow Plug Control Module		

<sup>\*)</sup> At a later date, Kit will supersede to individual Part Nos. as listed in table.

# Workflow Overview 2005 Model 2004 Model Verify Previous Required Vehicle **Update Technical Bulletin Group 97** No: 04-05 or 04-06 Completion BG, BH TB Work Nο **Procedure** performed Yes Install new fuel injectors, Glow Plugs and Glow plug relay Perform "Update Programming" No additional work required Perform applicable **BG** or BH procedure 27-A091

<sup>\*\*)</sup> To install injectors also requires bolts, (not included in kit) Part Nos: 038 103 714A (qty 8) and 038 103 385A (qty 4).





Part numbers listed in this T.B. are for reference only. Always check with your Parts Dept. for the latest parts information.

# (!) Note:

Ignition key must remain OFF until all parts have been replaced.

- Install new fuel injectors (see Repair Manual Group 23 - Mixture preparation, Injection, Unit injector, removing and installing)
- Install new engine Glow plugs -Q6-.
- ◆ Golf Jetta (see Repair Manual Group 28 -Glow plug system, Glow plug system, checking).
- ◆ New Beetle (see Repair Manual Group 28 Glow plug system, Glow plugs, servicing).
- Install new Glow activation control module -J370- (for location see Repair Manual Component locations).

With Parts replaced as necessary:

- Update ECM software using Flash CD W42TDISWU7000.



◆ DO NOT install this software update if injectors, glow plugs and glow plug relay as listed on page 1 have not been installed. Damage to glow plugs will occur.



### Procedure:

**Update - Programming (Flashing)** 



- ◆ When performing the reflash procedure. ALL DTCs for all systems are erased.
- ◆ DTCs linked to Guided Fault Finding function tests will be lost. Therefore, always address stored DTCs for Customer concerns unrelated to the reflash procedure first.



- ◆ The following "Update Programming" (flashing) process may overwrite any "TUNED" ECM programming.
- ◆ A "TUNED" ECM is described as any ECM altered so as to perform outside the normal parameters and specifications approved by Volkswagen of America, Inc..

If you encounter a vehicle with a "Tuned" ECM, prior to performing the "Update - Programming" (flashing) procedure:

- Your Dealership should place the vehicle owner on notice in writing, that their ECM was found to have been tuned, and that any damage caused by the tuning of the ECM (including any adverse emissions consequences) will not be covered by Volkswagen of America, Inc. warranties.
- For any repair requested by the owner under warranty or outside warranty that requires flashing, which will automatically wipe out the "Tuning" program, your Dealership should advise the owner of the above and get Owner's written consent (see attached Control Module Tuning form) to the flashing procedure.



### **Tool requirements**

- ◆ VAS 5051 or 5052 (with Basis CD V.07.55 and the Brand CD V.07.00 or higher) with old diagnosis logs erased prior to start.
- ◆ "Update Programming" (flashing) CD W42TDISWU7000.
- Approved battery charger.



Additional "Update copies of the Programming" (Literature CDNumber W42TDISWU7000) may be ordered from the Volkswagen Technical Literature Ordering Center at www.vw.ddsltd.com, or by calling 1-800-544-8021 from 8:00 a.m. to 8:00 p.m. EST Monday through Friday. This number can be dialed in both the United States and Canada.

## Vehicle requirements

- ◆ Battery MUST have minimum no-load charge of 12.5V (failure to maintain voltage during update process can lead to ECM failure) (use an approved battery charger to maintain battery voltage).
- ◆ VAS 5051: connected to vehicle and to 110V AC Power supply at all times during procedure.
- ◆ VAS 5052: connected to vehicle with battery voltage requirements met.
- ◆ Any appliances with high electromagnetic radiation (i.e. mobile phones) switched OFF.
- ◆ No Stored DTC's, erase any stored DTCs (see Tip on page 7).




# Please give copies to all Technical Bulletin your VW Technicians

# Note:

- ◆ Non-observance of the following points may lead to ECM failure!
- ◆ VAS 5051 or 5052 must always be connected to the approved power supply at approved voltages. Under no circumstances should the power supply be interrupted or the diagnostic connector unplugged during the flash procedure.
- ◆ Any appliances with high electromagnetic radiation (i.e. mobile phones) must be switched OFF.





"Update Programming" (flashing) procedure, checking for update match

- Switch ignition ON.
- Switch VAS 5051/5052 ON and insert flash CD into CD drive as soon as start screen appears.



You must return to the start screen before starting a new (flashing) session, otherwise the flashing CD will not be recognized by the tester.

- Select "Vehicle Self Diagnosis" mode.
- vehicle "01-Engine Select system electronics".
- ◆ Program checks software level.

If software level of ECM MATCHES level indicated by Flashing CD:

◆ "Update - Programming" (arrow) will not appear.




The "Update - Programming" function is only available when the inserted flashing CD level and current vehicle ECM level are different.

If "Update - Programming" does not appear:

- Programming (flashing ECM) cannot be performed, continue to diagnose condition.


If software level DOES NOT match the level indicated on Flashing CD:

◆ "Update - Programming" (arrow) appears.





# Please give copies to all Technical Bulletin your VW Technicians



PRIOR to performing procedure "Update - Programming" (flash) the ECM:

◆ ALL fault memories must be interrogated and erased.




Failure to erase ALL fault memories may cause "Update - Programming" (flashing) procedure to fail!

- Select Diagnosis function 06 "End output".
  - Select Diagnosis function 00 "Collection services".
  - Select "Check DTC memory complete system". which will interrogate all fault memories.



- ◆ When performing the reflash procedure, ALL DTCs for all systems are erased.
- ◆ DTCs linked to Guided Fault Finding function tests will be lost. Therefore, always address stored DTCs for Customer concerns unrelated to the reflash procedure first.
- Erase ALL fault memories.



Once ALL fault memories have been erased:

- Select vehicle "01-Engine system electronics".
- Select "Update Programming" option at bottom of screen (arrow).




# ① Note:


Once "Update - Programming" function has been started, switching ignition OFF or disconnecting the diagnostic connector may completely destroy the ECM.


C 23-05-02



Please give copies to all Technical Bulletin your VW Technicians







"Update - Programming" (flashing), performing

- After selecting "Update Programming" function, new program version as listed below will install:
  - ◆ 7000 for ECM Part No: 038 997 016 C. (Golf, Jetta, Jetta Wagon)
  - ◆ 7000 for ECM Part No: 038 997 016 D. (New Beetle)
  - ◆ Approximate timing for update is shown on the VAS 5051/5052 screen.
  - By selecting the 
     button, the programming procedure begins.
- Similar screen appears:

The previous data in the ECM is erased and the new data is being transferred to the module from the flash CD.



- ◄ If, during the "Update Programming", a fault message is displayed:
  - Confirm that VAS 5051 or VAS 5052 diagnostic tool power supply is adequate and that ALL appliances with high electromagnetic radiation (i.e. mobile phones) are switched OFF.
  - The "Update Programming" (flashing) process must then be started from the beginning using the "Repeat" button (arrow).
     DO NOT use the "Cancel" button.


8 of 11 plus attachment

C 23-05-02





On NO occasion should the "Cancel" button be selected.




Once "Update - Programming" (flashing) is complete:

- ◆ Similar screen appears.
  - ◆ ECM Part Number and old software level is still displayed at (arrows).



New software level is not displayed until process is complete and fault memories have been erased.

- Select the "Print", then "Screen" button.
- Attach print to vehicle Repair Order.




Once "Update - Programming" (flashing) is complete, the control module must be re-initialized.

- Select the 
   button.
- The tester requests you to switch the ignition OFF.
  - Switch ignition OFF.
  - ◆ The tester requests you to switch the ignition ON.
  - Switch ignition ON when prompted.

After switching ignition ON, the ECM has been re-initialized, however, fault memories must now be erased.

Select the "Continue button"





Fault memories, erasing after "Update - Programming" (flashing)

Due to the CAN bus system, fault messages will be stored in various Control Modules during programming.

- To erase ALL fault memories:
  - Confirm by selecting the ▶ button.

Vehicle Self-Diagnosis Update Programming	01 - Engine electronics ECM Part Number		
DTC memories are erased Function ended	ECM description & software level Coding XXXXXX Dealership number XXXXX		
Vehicle systems with erased fault	t memories:		
01 - Engine electronics	225		
02 - Gearbox electronics			
03 - Brake electronics	Section of the Control of the Contro		
15 - Airbeg			
25 - Immobilizer	DECEMBER OF STREET		
16 - Steering wheel electronics			
46 -Convenience system central i	module		
56 - Radio			
17 - Dash panel insert	7 28C 38CA		
Function ended!			
Test Go t	o Print ? 🛕		
	01-A325		

Once fault memories have been erased:

- Similar screen appears.
  - ◆ Old ECM Part No. and software level still appear at (arrow).
  - Function ended appears at bottom of screen.
  - Finish update of the ECM by selecting the ◀ button.

Vehicle Self-Diagnosis Select Giagnosis function	01 - Engine electronics ECM Part Number ECM description and software leve Coding XXXXXX	
02 - interrogate fault memory 03 - Final control diagnosis 04 - Basic settings 05 - Erase fault memory 06 - End output 07 - Gode control unit 08 - Read data block 09 - Reading individual measurin 10 - Adaption 11 - Log-in procedure	Dealership number XXXXX	
Go	to Print ? 🛕	
	01-A326	

- ◆ Similar screen appears.
- ◆ Updated software level "7000" will appear at (arrow).
  - ◆ Flash CD can now be removed from VAS 5051 or VAS 5052 Diagnostic tool.
  - Print the ECM screen to verify ECM update software level.
  - Attach print to vehicle Repair Order.
  - Select "Go to" then select "Exit".

C 23–05–02 10 of 11 plus attachment



# Please give copies to all Technical Bulletin your VW Technicians



It is not generally necessary to encode the ECM following the "update - Programming" (flashing procedure. However, you must set the readiness code.

- Set readiness code.
- Use VAS 5051 or VAS 5052 to set readiness code.

When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:		
Claim Type:	W2	
Part Identifier:	2338	
*Damage Code:	2338 10 xxx 2	
Labor Operation:	2338 2036 250 TU	
Replace injectors		
Labor Operation: Replace Glow Plugs	2884 2000 70 TU	
Labor Operation:	2885 1900 30 TU	
Replace Control Module		
Labor Operation:	2338 2540 90TU	
Update programming		
Diagnostic Time:	No Diagnostic time allowed	
Claim Comment: Type "Per Technical Bulletin V230501" in comment section of Warranty claim.		

<sup>\*)</sup> xxx = vendor code for part



# OWNER INFORMATION ABOUT CONTROL MODULE TUNING\* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

*) "TUNING" is described as the addition of or modification of any convolkswagen vehicle to perform outside the normal parameters and sp Volkswagen of America, Inc	
Date:	
Dealer Number:	
Vehicle Identification Number:	
Repair Order Number:	
	Dealer stamp
I, owner or driver of the above identified	Volkswagen, confirm:
☐ "Tuning" as described above (especially power increasing modifiperformed on my vehicle.	cations) has NOT been
Tuning" as described above has been performed on my vehicle and were modified or installed:	the following components
TUNING was performed by (Please provide Company name and telephoto contact them):	ne number, if you wish us
I understand that if my Control Module is determined to have been tuned the tuning of the Control Module (including adverse emissions conseque by Volkswagen of America, Inc. warranties.	
I am permitting an authorized Volkswagen Dealer to reflash (update) my doing so, I understand that this process will automatically overwrite (delete any tuning program that was previously installed on the Control M vehicle.	estroy) and permanently
By signing below, I fully acknowledge and understand that the tuning pro and Volkswagen of America, Inc., will not be liable in any way for the los	
Signature	of Customer