

PAGE 1 OF 2

CUSTOMER COPY

Volkswagen of South Charlotte

VWCS166109

9900 SOUTH BOULEVARD • CHARLOTTE, NC 28273 • PHONE (704) 552-6500

USTOMER NO.	18538		ADVISOR ADAM	MIKE	LS		519	g NO. 4031	01/09/19	VWCS166109
		_	LABOR F	ATE	LICENS	E NO.	MILEA	132,513	COLOR /	STOCK NO.
			YEAR / N	AKE / MODEL	A CEN /	ICTTA /	4DD 140		DELIVERY DATE	DELIVERY MILES
CHARLOTTE, NC 28278-7830				10/VOLKSWAGEN/JETTA/4DR WGN DSG TD3					SELLING DEALER NO.	PRODUCTION DATE
							P. O. NO.		R. O. DATE	
			F. T. E. NO).			P. O. NO.		01/08/19	
SIDENCE PHONE		BUSINESS PHONE	COMMEN	ITS						MO: 13252
ARTSQ DB # 1 DB # 1	CUSTOMER STATES CHECK ENGINE LIGHT ON 352 VC: VDO - INTAKE MANIFOLD TEST DROVE VEHICLE, CONFIRMED CUSTOMER CONCERN THAT THE CEL IS ILLUMIANTED. SCANNED VEHICLE FOR FAULTS, FAULT STORED FOR P2015 INTAKE MANIFOLD RUNNER POSITION SENSOR RANGE/ PERFORMANCE. RAN TEST PLAN IN GFF CHECKING WIRING TO AND CONNECTION AT INTAKE MANIFOLD - WIRING OK. DETERMINED PER GFF THAT MANIFOLD RUNNER HAS INTERNAL CIRCUIT MALFUNCTION. REMOVED FUEL LINES AND FUEL RAIL, EGR VALVE TO GAIN ACCESS. REPLACED INTAKE MANIFOLD AND ADAPTED TO ECM. VENTED FUEL SYSTEM AND STARTED ENGINE. NO FAULTS STORED FOR INTAKE MANIFOLD. TEST DROVE VEHICLE TO ENSURE FIX. YFP-NUMBER								hereby are those made by the manufacturer. The seller, VOLKSWAGEN OF SOUTH CHARLOTTE, hereby expressive disclaims all warranties, either expression implied, including any implied warranty of merchantability or fitness for a particular purpose, and VOLKSWAGEN OF SOUTH CHARLOTTE neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. I hereby authorize the repair work to be done along with the necessary material and hereby grant you and or you employees permission to operate the car or truck hereid described on streets, highways or elsewhere for the pupose of testing and or inspection. An express mechanic	
JOB # 1 TOTAL LABOR & PARTS 0.00 J# 2 10VHZ ENGINE PERFORMANCE TECH(S):352 WARRANTY C/S THE GLOW PLUG LIGHT WAS FLASHING AT THEM THIS AFTERNOON 352 VC: VDO - SIEMENS - THROTTLE VALVE TEST DROVE VEHICLE, CONFIRMED CUSTOMER CONCERN THAT THE CEL IS ILLUMIANTED. SCANNED VEHICLE FOR FAULTS, FAULT STORED P0638 FOR THROTTLE VALVE CONTROL BANK 1 RANGE PERFORMANCE. RAN TEST PLAN IN GFF CHECKING WIRING TO AND CONNECTION AT THROTTLE VALVE - ALL OK. DETERMINED THROTTLE VALVE IS STICKING AT TIMES AND INHIBITING PROPER THROTTLE CONTROL FRO M ECM. REMOVED AND REPLACED THROTTLE VALVE AND ADAPTED TO								lien is hereby acknowledged on below car or truck to secun the amount of repairs thereto. Not responsible for an delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. It is agreed an understood that if the purchases listed below are not pai when due. I, we or either of us agree to pay all attorne fees and all other costs which may be incurred in the collection of this account. All repairs are considered satis factory unless we are advised (in writing) within ten day from the date of this order. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEF OR ANY OTHER CAUSE BEYOND OUR CONTROL.		
	ECM. TEST DR	OVE VEHICLE TO	D ENSURE FIX.						CASH - CHECK	OR CREDIT CARD
	1 03G-1 1 069-1		DESCRIPTION CONTR.UNIT GASKET ING ORDERED			2 TOTAL	PARTS	WARRANTY WARRANTY 0.00 0.00	12 M	RER'S WARRANTY IONTHS OR IO MILES
			(Uz 9263	7 19 19	0.00		R COMES FIRST
	COURTESY VEH	ICLE CHECK	DESCRIPTION	JOB #	JOB #	3 TOTAL LABOR &	PARTS PARTS	0.00		

[CONTINUED ON NEXT PAGE]