

AN31.19-D-8100-05NA	Retrofit trailer hitch wiring harness		
 WS	000 588 11 62 00 Major assembly mount		WS01.00-P-0092B

Model 906.1/6/7
with code ZU7 (National version for Canada)
except code E40 (Trailer socket, 7-pin)
except code E58 (Electrics for trailer socket)
except code ZU8 (National version for USA)
except code ZU9 (National version for Mexico)

Model 906.1/6/7
with code ZU8 (National version for USA)
except code E40 (Trailer socket, 7-pin)
except code E58 (Electrics for trailer socket)
except code ZU7 (National version for Canada)
except code ZU9 (National version for Mexico)


Model 906.1/6/7
with code ZU9 (National version for Mexico)
except code E40 (Trailer socket, 7-pin)
except code E58 (Electrics for trailer socket)
except code ZU7 (National version for Canada)
except code ZU8 (National version for USA)

Modification notes


08.03.2016	Multiplug (3a) to be detached from fuse and relay module (K40/9) modified.	Operation step 13	
08.03.2016	Contact cavity and slot for pinning terminal 54 line (3) changed.	Operation step 14	

Fuel tank

Number	Designation		Model 906 with engine 642, 646, 651
BA47.10-N-1002-01E	Bolt, fuel tank tensioning strap to longitudinal member	Nm	56



220 589 04 99 00
New passenger car wiring harness repair kit



000 589 13 99 00
Wiring harness repair kit, basic