HST2 Page 1 of 1

Problem description

Cold starting problems, engine difficult to start and misfires. On vehicles with transparent fuel pipes big bubbles can clearly be seen during the start-up.

Cause

Air is drawn into the fuel system through leaks in the fuel system, on pipes, pipe connections, fuel prewarming valve and faulty fuel gauge sender unit.

Production solution

Various changes.

Service solution

Check the complete fuel systems for leaks.

If no fault is found, replace the fuel gauge sender unit.