



AHU and 1Z serpentine belt tensioner parts, should be replaced every other timing belt (120K intervals)

<u>Qty</u>	<u>Pos #</u>	<u>VW PN#</u>	<u>Description</u>
1	1	<b>b 028 145 278 E</b>	78mm roller with Threaded bushing
1	2	<b>028 145 291 B</b>	Protective cap only for: b 028 145 278 E
2	7	<b>028 903 310</b>	Dust cap
1	8	<b>037 903 315 C</b>	Tensioner
1	11	<b>N 014 740 4</b>	Allen Key Head bolt M6X16
1	12	<b>N 019 533 4</b>	Hexagon Head bolt c/w shoulder M8X20
2	16	<b>N 014 709 1</b>	Allen Key Head bolt M8X22