

Saturday,20,January,2018,13:53:33:49225
VCDS -- Windows Based VAG/VAS Emulator Running on Windows 10 x86
VCDS Version: 17.8.1.0
Data version: 20171130 DS276.6
www.Ross-Tech.com

VIN: 3VWST71K06M703867 License Plate: CHRIS
Mileage: 172630km-107267mi Repair Order:

Chassis Type: 1K (1K0)
Scan: 01 03 08 09 0F 15 16 17 19 25 42 44 46 52 56 62 72 7D

VIN: 3VWST71K06M703867 Mileage: 172630km-107267miles

00-Steering Angle Sensor -- Status: OK 0000
01-Engine -- Status: OK 0000
03-ABS Brakes -- Status: OK 0000
08-Auto HVAC -- Status: OK 0000
09-Cent. Elect. -- Status: Malfunction 0010
0F-Digital Radio -- Status: Malfunction 0010
15-Airbags -- Status: OK 0000
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
19-CAN Gateway -- Status: Malfunction 0010
25-Immobilizer -- Status: OK 0000
42-Door Elect, Driver -- Status: Cannot be reached 1100
44-Steering Assist -- Status: OK 0000
46-Central Conv. -- Status: Malfunction 0010
52-Door Elect, Pass. -- Status: OK 0000
56-Radio -- Status: Malfunction 0010
62-Door, Rear Left -- Status: OK 0000
72-Door, Rear Right -- Status: OK 0000
7D-Aux. Heat -- Status: OK 0000

Address 01: Engine Labels: 038-906-016-BEW.lbl
Part No SW: 03G 906 016 AB HW: 028 101 223 8
Component: R4 1,9L EDC G000SG 7550
Revision: --H01--- Serial number: VWZ7Z0E2762871
Coding: 0050071
Shop #: WSC 00066 000 00000
VCID: 63CEAFDBA295F15EEC-8036

No fault code found.
Readiness: 0 0 0 0 1

Address 03: ABS Brakes Labels: 1K0-907-379-MK60-F.lbl
Part No SW: 1K0 907 379 Q HW: 1K0 907 379 Q
Component: ESP FRONT MK60 0102
Revision: 00T12001
Coding: 0021122
Shop #: WSC 00066 000 00000
VCID: 4084405713438A46D1-8014

No fault code found.

Address 08: Auto HVAC Labels: 1K0-820-047.lbl
Part No: 1K0 820 047 DL
Component: Climatic PQ35 090 0505
Shop #: WSC 00000 000 00000
VCID: 71E2D593686953CE6E-8024

No fault code found.

Address 09: Cent. Elect. Labels: 3C0-937-049-23-M.lbl
Part No SW: 3C0 937 049 D HW: 3C0 937 049 D
Component: Bordnetz-SG H37 1002
Revision: 00H37000 Serial number: 00000000182075
Coding: 14018E234004180000140000001400000008730B5C
Shop #: WSC 05052 444 52349
VCID: 2A5002FF853F6016EF-807E

Subsystem 1 - Part No: 1K1 955 119 C Labels: 1KX-955-119.CLB
Component: Wischer VW350 012 0402
Coding: 00065493
Shop #: WSC 05052

1 Fault Found:

01331 - Door Control Module; Driver Side (J386)

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100
Fault Priority: 2
Fault Frequency: 1
Reset counter: 137
Mileage: 172630 km
Time Indication: 0

Freeze Frame:

ON
Voltage: 12.00 V
ON
ON
OFF
OFF
OFF

Address 0F: Digital Radio Labels: 8E0-035-593-SIR.lbl
Part No SW: 8E0 035 593 D HW: 8E0 035 593 D
Component: SDAR SIRIUS H03 0060
Revision: 00000000 Serial number: AUZ4Z7F5019749
Shop #: WSC 00000 000 00000
VCID: 2A5002FF853F6016EF-807E

1 Fault Found:

02635 - Tuner Not Enabled/Activated

000 - -

Freeze Frame:

Fault Status: 01100000

Fault Priority: 7

Fault Frequency: 1

Reset counter: 137

Mileage: 172630 km

Time Indication: 0

Date: 2000.00.00

Time: 02:00:37

Address 15: Airbags Labels: 1K0-909-605.lbl
Part No SW: 1K0 909 605 E HW: 1K0 909 605 E
Component: 1S AIRBAG VW8R 024 6300
Revision: 03024000 Serial number: 0037KD049RSP
Coding: 0012627
Shop #: WSC 00066 000 00000
VCID: 2E580EEFB9D70C3633-807A

Subsystem 1 - Part No: 1K0 959 339 E

Component: BF-Gewichtsens. 006 0005

Subsystem 2 - Serial number: 6332MSME0A1E40112

Subsystem 3 - Serial number: 6342MSME0A335A7EO

Subsystem 4 - Serial number: 6351HSME083F634CI

Subsystem 5 - Serial number: 6361HSME08335056+

Subsystem 6 - Serial number: 63727SME077B543EB

Subsystem 7 - Serial number: 63827SME08022100H

No fault code found.

Address 16: Steering wheel Labels: 1K0-953-549-MY8.lbl
Part No SW: 1K0 953 549 AH HW: 1K0 953 549 AH

Component: J0527 034 0070
Coding: 0000021
Shop #: WSC 00066 000 00000
VCID: 78F4E8B70B130286A9-802C

No fault code found.

Address 17: Instruments Labels: 1K0-920-xxx-17.lbl
Part No: 1K0 920 952 D
Component: KOMBIINSTRUMENT 3HL 1212
Coding: 0023203
Shop #: WSC 00066 000 00000
VCID: 2B5E07FB8AC5791E14-807E

No fault code found.

Address 19: CAN Gateway Labels: 1K0-907-530-V1.clb
Part No SW: 1K0 907 530 F HW: 1K0 907 951
Component: Gateway H10 0120
Revision: H10 Serial number: 28001059019549
Coding: 3D3F0B60071002
Shop #: WSC 00066 000 00000
VCID: 2A5002FF853F6016EF-807E

1 Fault Found:

01331 - Door Control Module; Driver Side (J386)

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100
Fault Priority: 2
Fault Frequency: 1
Reset counter: 137
Mileage: 172630 km
Time Indication: 0
Date: 2000.00.00
Time: 02:00:36

Address 25: Immobilizer Labels: 1K0-920-xxx-25.clb
Part No: 1K0 920 952 D
Component: IMMO 3HL 1212
Shop #: WSC 05052 444 59220
VCID: 2B5E07FB8AC5791E14-807E

No fault code found.

Address 42: Door Elect, Driver
Cannot be reached

Address 44: Steering Assist Labels: 1Kx-909-144-G2V2.clb
Part No: 1K1 909 144 J
Component: EPS_ZFLS KI.5 D04 1606
Shop #: WSC 00000 000 00000
VCID: 32601A9FADEF28D657-8066

No fault code found.

Address 46: Central Conv. Labels: 1K0-959-433-MIN.clb
Part No: 1K0 959 433 AF
Component: KSG 0401
Coding: 137803281B09058F880F048051A0
Shop #: WSC 00066 000 00000
VCID: 74ECDC87177B66E685-8020

Subsystem 1 - Component: Sounder n.mounted

Subsystem 2 - Component: NGS n.mounted

Subsystem 3 - Component: IRUE n.mounted

1 Fault Found:

01331 - Door Control Module; Driver Side (J386)
004 - No Signal/Communication

Address 52: Door Elect, Pass. Labels: 1K0-959-702-MIN2.lbl
Part No: 1K0 959 702 K
Component: Tuer-SG 024 2377
Coding: 0001269
Shop #: WSC 00066 000 00000
VCID: 37762B8B468DCDFE60-8062

No fault code found.

Address 56: Radio Labels: 1K0-035-1xx-56.lbl
Part No SW: 1K0 035 180 C HW: 1K0 035 180 C
Component: Radio DE2 011 0014
Revision: 00011000 Serial number: VWZ4Z7E2044364
Coding: 0010400
Shop #: WSC 00000 000 00000
VCID: 2044E0D7F303AA46B1-8074

1 Fault Found:

00003 - Control Module
014 - Defective

Address 62: Door, Rear Left Labels: 1K0-959-703-GEN2.lbl
Part No: 1K0 959 703 D

Component: Tuer-SG 021 2434
Coding: 0000144
Shop #: WSC 00066 000 00000
VCID: 31621593A8E913CE2E-8064

No fault code found.

Address 72: Door, Rear Right Labels: 1K0-959-704-GEN2.lbl
Part No: 1K0 959 704 D
Component: Tuer-SG 021 2434
Coding: 0000144
Shop #: WSC 00066 000 00000
VCID: 32601A9FADEF28D657-8066

No fault code found.

Address 7D: Aux. Heat Labels: 1K0-963-235.lbl
Part No SW: 1K0 963 235 E HW: 1K0 963 235 E
Component: PTC-Element 0404
Revision: 00800000 Serial number:
Shop #: WSC 00000 000 00000
VCID: 2D5A09E3B4D1772E0A-8078

No fault code found.

End----- (Elapsed Time: 02:11)-----